

Product Change Notification



Title:	FCB Kit Mounting Screws
Our reference:	CN-0012-01
Date:	8th June 2015
For further information contact:	Email: sales@activesilicon.com Europe: +44 (0)1753 650600 USA: +1 410-696-7642

Product(s) affected:	Active Silicon products affected by this change: <ul style="list-style-type: none"> • HD-SDI digital interface kit for Sony FCB-H11: AS-HDSDI-IFKIT-A • HD-SDI digital interface kit for Sony FCB-EH Series: AS-HDSDI-003-IFKIT-A • HD-SDI digital interface kit for Sony FCB-EH3150: AS-HDSDI-003-IFKIT-B • HD-SDI digital interface kit for Sony FCB-EV Series: AS-HDSDI-004-IFKIT-A • HD-SDI digital interface kit for Sony FCB-EV7100: AS-HDSDI-004-IFKIT-B
Description of change:	Recent additions to the Sony FCB block camera range require the use of M2 x 4 screws for mounting the Active Silicon supplied bracket to the camera. After reviewing existing cameras in the FCB range it was found that the screws supplied with the existing kits (listed above) are longer than Sony recommends. In practice there does not appear to be a problem with clearance on these models, however the current screws will be updated as described above so that they are within the tolerances specified by Sony. For ALL the above kits: The M2 x 6 (countersunk) screws are replaced with M2 x 4 (countersunk) screws. In addition to this, the AS-HDSDI-003-IFKIT-B has the following change: The M2 x 10 (countersunk) screws are replaced with M2 x 8 (countersunk) screws.
Affect that change has on operation:	None
How to identify original and changed product:	Check the build issue on the product box label. The following issues have the above change applied: Iss 01A Iss 02A or higher
Date that changed product will be shipped:	The change is effective immediately.
Notes:	None.