Product End-of-Life Notice

Phoenix HD-SDI Frame Grabbers



Description:	 This notice is to announce the "End-of-Life" (EOL) status of the Phoenix HD-SDI frame grabber product range. Products targeted for end-of-life will be available for a last time buy purchase prior to being made obsolete. At the same time, we would like to inform that we are no longer upgrading frame grabber drivers for these HD-SDI boards. Latest driver versions: Phoenix Driver (Windows 32 and 64-bit) v6.64 Driver for CatalystPM (Mac OS X) v5.43.6 DMG, running on v10.10 Yosemite and Mac Pro 6.1 (drivers for earlier Mac OS X ver. available) 		
Products affected:	AS-PHX-D10HDSDI-PE4H A	AS-PHX-D10HDSDI-PE1	
	AS-PHX-D20HDSDI-PE4H A	AS-PHX-D20HDSDI-PE1	
	Frame grabber drivers for the boards mentioned above		
Date of this EOL notice:	02 July 2018		
Products original release date:	2008		
Reason for the EOL:	Due to the obsolescence of key components used in the manufacture of the Phoenix HD-SDI frame grabber products we are facing increased difficulties producing these boards.		
Last Time Buy Date:	03 December 2018		
	We are offering a Last-Time-Buy (LTB) allowing customers to place final orders. The products listed above will no longer be for sale after this date.		
	Although we will make every effort to fulfil LTB orders, the acceptance of these orders is subject to product availability. We encourage customers to contact Active Silicon to discuss their LTB requirements.		
Last Time Delivery Date:	02 July 2019		
Suggested alternatives:	Please contact Active Silicon to discuss alternative solutions.		

Direct replacement:	None		
Reference:	DN-AP06-0010		
For further information:	Web: Email: Europe: USA:	www.activesilicon.com sales@activesilicon.com +44 (0)1753 650600 +1 410-696-7642	