


Product Change Notification



| | |
|---|--|
| Title: | Camera Link Cable Thumbscrews |
| Our reference: | CN-0011-01 |
| Date: | 10th September 2014 |
| For further information contact: | Email: sales@activesilicon.com Europe: +44 (0)1753 650600 USA: +1 410-696-7642 |

| | |
|--|--|
| Product(s) affected: | All Camera Link cables. |
| Description of change: | The use of 1mm longer thumbscrews on the cable. |
| Affect that change has on operation: | This gives better engagement with the threads on existing cameras, but still with a low risk of bottoming out at the bottom of the jackpost. |
| How to identify original and changed product: | |
| Date that changed product will be shipped: | - |
| Notes: | - |

Original



Changed

Figure 1: Camera Link Cable shown with original and changed thumbscrews